

#### Description

The clean way to remove sticky labels. Solvent based blend for the removal of sticky labels from most substrates including many plastics, metals, rubbers, painted surfaces and other impervious materials, leaving no residues or markings.

#### Benefits & Features

- Dissolves gums and adhesives from self adhesive labels
- Suitable for most surfaces
- Leaves no residues
- High penetrating power

#### Directions for Use

Shake can well before use and spray liberally onto label or adhesive residue from a distance of 20 to 30cm, ensuring complete coverage. Leave to penetrate and peel or scrape away label once it has turned transparent. A second application may be required for thicker or less porous labels. **Test for suitability on an inconspicuous area first, particularly on thermoplastics or unknown substrates.**

#### Technical Data

Appearance:	Clear colourless free flowing liquid
Odour:	Strong solvent
Contents:	Blend of propan-2-ol and naphtha with propane and butane propellant
Flash Point:	<0°C
Solubility:	Insoluble in water
Temperature Range:	Designed for use at ambient temperatures
Relative Density:	0.735
Flammability:	Extremely Flammable
Health & Safety:	Consult Safety Data Sheet (available at tygrisindustrial.com)
Storage:	Below 50°C
Pack Size:	12 x 400ml aerosols



#### Note

This technical data sheet is for general guidance purposes only and may contain information that is inappropriate for certain conditions of use. Accordingly, all recommendations and suggestions are made without guarantee. Further information is available from our Technical Department.