



CAUTION: PROTECT BALLS AND RACES FROM SAWDUST, DIRT, PAINT, ETC. SHOULD BEARING BECOME "ROUGH" FROM DIRTY RACES, FLUSH THOROUGHLY WITH HOT SOAPY WATER, RINSE, OVEN DRY AND RE-OIL.



THERE MAY BE 2 TO 4 BALLS LEFT OUT DUE TO MANUFACTURING PROCESS.

PART STAMPED WITH TRIANGLE NAME STAMP

3	BALLS12	BALL	1
2	1866	PLAIN RACE	1
1	1865	LOCKING RACE	1

DET	PART NUMBER	DESCRIPTION	AMT
C TRIANGLE MANUFACTURING CO.			
NAME 12" LAZY SUSAN BRG. ASSY			

FIT		////	USED IN	////
PLATING		ELECTRO GALV	DATE	7-14-76
MATERIAL		SEE DETAIL	DRAWN	LML
ALL DIMS. 1.020 UNLESS OTHERWISE SPECIFIED			CHECKED	SP
		SCALE	1 / 1	12C

CHANGE LEVEL
P 07-31-06